



## NUOVO ARTICOLO 2016 NEW ITEM 2016

|                              |                         |   |
|------------------------------|-------------------------|---|
| <b>CODICE ARTICOLO</b>       | <b>REFERENCE NO.</b>    | <b>09010262 / 09010263</b>  |
| <b>DESCRIZIONE</b>           | <b>ITEM DESCRIPTION</b> | <b>FRAMMENTO VANO MOTORE DESTRO / SINISTRO<br/>REPAIR PANEL FOR ENGINE COMPARTMENT RIGHT / LEFT</b> |
| <b>SIMILE A</b>              | <b>SIMILAR TO</b>       |   |
| <b>MARCA</b>                 | <b>MANUFACTURER</b>     | <b>FIAT</b>   |
| <b>MODELLO</b>               | <b>CAR MODEL</b>        | <b>500 F/L/R</b>  |
| <b>TIPO VETTURA</b>          | <b>TYPE OF CAR</b>      |   |
| <b>1 PC = KG</b>             |                         | <b>0,200</b>  |
| <b>1 M<sup>3</sup> = PCS</b> |                         | <b>500</b>  |
| <b>DATA</b>                  | <b>DATE</b>             | <b>02/2016</b>  |

09010262

